

2011-27-51 Hawker Beechcraft Corporation: Directorate Identifier 2011-CE-044-AD.

(a) Effective Date

This Emergency AD is effective upon receipt.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the following Hawker Beechcraft Corporation airplanes, certificated in any category:

	Models	Serial Numbers
(1)	1900	UA-3
(2)	1900C	UB-1 through UB-74 and UC-1 through UC-174
(3)	1900C (Military)	UD-1 through UD-6
(4)	1900D	UE-1 through UE-439

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by reports of the elevator bob-weight (stabilizer weight) traveling past its stop bolt, which allowed the attaching linkage to move over-center. We are issuing this AD to detect and correct conditions that could result in reduced nose down elevator control and loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections

Within the next 10 hours time-in-service after receipt of this emergency AD, inspect the elevator bob-weight installation for the following conditions. Use Hawker Beechcraft Corporation Safety Communiqué #321, dated December 2011.

NOTE: The term “nose down” corresponds to the airplane nose down, down elevator, and control column forward position as used in this AD and Hawker Beechcraft Corporation Safety Communiqué # 321, dated December 2011.

(1) The correct positioning of the elevator control column link assembly, (part number (P/N) 101-524112-1 (1900/1900C) or P/N 101-524112-5 (1900D)). With the elevator control column in the full nose down position (control column forward), the link must form an angle between the link attachment point at the control column and the bell crank pivot point as shown in the Hawker Beechcraft Corporation Safety Communiqué photo labeled “Correct Link Orientation.” The link should be trailing AFT from the control column assembly.

(2) The clearance of the bob-weight stop bolt. With the elevator control column in the full nose down position (control column forward), the stabilizer weight stop bolt must have positive clearance with the face of the stabilizer weight.

(3) The condition of the bob-weight and alignment with the stop bolt. Inspect for evidence of scraping along either side of the weight by the stop bolt. With side pressure applied by hand to the stabilizer weight, no part of the stop bolt should protrude beyond the face of the stabilizer weight on either edge.

(4) The condition of the bob-weight support bracket. Inspect for evidence of damage or deformation by contact with the weight assembly.

(h) Corrective Actions

If any discrepancies are found in the inspections required in paragraph (g) of this AD, before further flight, do the following:

(1) Contact Hawker Beechcraft Corporation Technical Support by telephone at (800) 429-5372 or (316) 676-3140 to obtain FAA-approved repair or replacement instructions.

(2) Incorporate the repair or replacement specified in the FAA-approved instructions.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For further information about this AD, contact one of the following:

(i) Paul DeVore, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4142; fax: (316) 946-4107; email: paul.devore@faa.gov; or

(ii) Don Ristow, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4120; fax: (316) 946-4107; email: donald.ristow@faa.gov.

(2) For copies of the service information referenced in this AD, contact Hawker Beechcraft Corporation at P.O. Box 85, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140; Internet: <http://pubs.hawkerbeechcraft.com>.

(3) You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.